

BUILDING CONDITION ASSESSMENT

SHED 2 AT GRAVEL PITS

351028 17TH LINE
EAST GARAFRAXA, ONTARIO

Prepared for:

Township of East Garafraxa
65371 Dufferin County Rd 3,
East Garafraxa, Ontario
T: 226-259-9400
E: info@eastgarafraxa.ca

Prepared by:



25 First Street
Orangeville, Ontario L9W 2C8
519.940.0571
kellerengineering.com

December 15, 2023

CONTENTS:

1.0 EXECUTIVE SUMMARY..... 3

1.1 INTRODUCTION 3

1.2 GENERAL SITE DESCRIPTION..... 3

1.3 GENERAL SITE DETAILS 3

1.4 SUMMARY OF FACILITY CONDITION INDEX (“FCI”) 3

1.5 GENERAL CONDITION 4

1.6 RECOMMENDATIONS FOR FURTHER STUDY 4

2.0 PURPOSE AND SCOPE 4

2.1 PURPOSE 4

2.2 SCOPE & METHODOLOGY 4

2.3 STANDARDS OF REFERENCE..... 5

3.0 SYSTEMS AND OBSERVATIONS 7

3.1 SITE IMPROVEMENTS..... 7

3.1.1 PAVING & CURBING 7

3.1.2 FLATWORK 7

3.1.3 LANDSCAPING & APPURTENANCES 7

3.2 STRUCTURE & BUILDING ENVELOPE 7

3.2.1 SUBSTRUCTURE 7

3.2.2 SUPERSTRUCTURE 7

3.2.3 EXTERIOR 7

3.2.4 ROOFING 8

3.3 MECHANICAL SYSTEMS..... 8

3.3.1 PLUMBING 8

3.3.2 HVAC..... 8

3.3.3 ELECTRICAL 8

3.4 SPECIAL SYSTEMS 8

3.4.1 SECURITY 8

3.4.2 FIRE PROTECTION & LIFE SAFETY 8

3.5 INTERIOR ELEMENTS..... 8

3.5.1 FINISHES 8

3.6 MISCELLANEOUS 9

3.6.1 MAINTENANCE & OTHER 9

4.0 REPAIR/ REPLACEMENT RESERVES 9

5.0 LIMITATIONS..... 9

APPENDICIES:

- Appendix A: SELECTED PHOTOGRAPHS
- Appendix B: FACILITY CONDITION INDEX TABLE
- Appendix C: RESUMES

1.0 EXECUTIVE SUMMARY

1.1 Introduction

Keller Engineering performed a Building Condition Assessment (“BCA”) of 351028 17th Line East Garafraxa, ON (“Site”) on October 24, 2023, on behalf of The Township of East Garafraxa (“Client”). The report that follows is based on that review. The weather was sunny and approximately 17°C.

Due to safety concerns, we were not able to review conditions up close and interior.

1.2 General Site Description

The Site is composed of 1 building. The building is a one-level structure that is not currently being used. The building was constructed in 1981. The building has a footprint of approximately 339 m² (5,078 ft²). The site area excluding the building is mainly trimmed grass, and trees. The surrounding area is primarily fields. The Site is accessed off 17th Line. For the purposes of this report, the building’s elevation facing 17th Line is facing east and is located on the west side of the 17th Line.

1.3 General Site Details

City/Town:	East Garafraxa
Province:	Ontario
Number of Stories:	1
Year Built:	1981
Structure:	Foundation, structural framing with prefabricated wood trusses.
Exterior:	Metal siding and wood windows.
Roof:	Sloped metal roof & sheet metal.
Plumbing:	Not applicable.
Heating, Ventilation & Cooling:	Ventilation fans. Not operational.
Electrical:	Not applicable.
Services:	Potable Water: Not applicable. Sewer: Not applicable. Storm: Not applicable, surface. Fuel: Not applicable. Electricity: Unknown.

1.4 Summary of Facility Condition Index (“FCI”)

The current condition of the building and components is expressed as a percentage derived from the ratio of aggregated total cost of repairs/renewal/upgrades to the current replacement value of the building. This ratio is referred to as the Facility Condition Index (“FCI”). Refer to **Appendix B** for a detailed description.

The aggregated total costs estimated for the building is \$736,560 adjusted for inflation. The current replacement value of the building is estimated to be \$720,000.00.

Based on the estimated values, the FCI for this building is 160% and is classified as Critical.

Refer to Section 2.3, Standards of Reference, for definitions and classifications.

1.5	General Condition	The building is in failure mode and has collapsed. All building components and systems are not safe and are no longer functional. The building is in critical condition and should be demolished.
1.6	Recommendations for Further Study	We have identified the need for a Structural Study, Life Safety Audit and Designated Substances Survey to review conditions to protect people based on building construction, protection, and occupancy features.
2.0	PURPOSE AND SCOPE	
2.1	Purpose	The purpose of this BCA is to determine the current condition of the building envelope, systems, paved areas, utilities, and site improvements, and to assign an FCI value for the building.
2.2	Scope & Methodology	<p>Keller Engineering, formerly Criterium-Jansen Engineers performed the BCA according to the scope as generally defined in ASTM 2018-15. The survey is based on a review of available documents, an examination of the building and the Site; in particular, the foundation walls (where visible), the roof, the exterior walls, the framing, exterior doors and windows, and utilities.</p> <p>The report contains the following:</p> <ul style="list-style-type: none"> • A description of the overall condition of buildings components and systems and conditions that may limit the expected useful life of the buildings and their components. • Information about significant deficiencies, deferred maintenance items, and material code violations based on a visual survey of the building and grounds, research of documents, and conversations with people who have knowledge about the facility. <p>The statements in the report are opinions about the present condition of the subject property. They are based on visual evidence available during a diligent review of all reasonably accessible areas. Standard BCA practices excludes the operation of equipment by the field observer and is to be conducted without the aid of special protective clothing, exploratory probing, removal or relocation of materials, testing, or the use of equipment, such as ladders, stools, scaffolding, metering/testing equipment, or devices of any kind, etc. It is literally the field observer’s visual observations while walking through the subject property. The study is not an exhaustive technical evaluation. Such an evaluation would entail a significantly larger scope than this effort. For additional limitations, see Section 5.0. As per standard BCA practices, the user of this report is required to arrange for the field observer to receive timely complete, supervised, and safe access to the subject property’s improvements including roofs. Where access was not provided Keller Engineering is obligated to state within the report all such material impediments that interfered with the conducting of the assessment.</p> <p>Our mandate for this BCA excluded assessment of the facility’s compliance to accessibility related standards and the Accessibility for Ontarians with Disabilities Act. Barrier Free Design of the National Building Code of Canada governed handicap accessibility guidelines for buildings constructed after</p>

2.3 Standards of Reference

1990. Possible retroactive compliance for buildings constructed prior to 1990 was not required until subsequent provincial legislation was enacted. A significant change of building use or an Authority Having Jurisdiction may trigger the need for accessibility related building upgrades under certain circumstances. As the timing, scope of work and associated costs cannot be reasonably predicted, we have not included any Capital Costs for future upgrades in the term of the report.

For your reference, the following definitions may be helpful:

All ratings are determined by comparison to other buildings of similar age and construction type.

All directions (left, right, rear, etc.) are taken from the viewpoint of an observer standing in front of the building and facing it.

Condition

Excellent: Component or system is in "as new" condition, requiring no rehabilitation and should perform in accordance with expected performance.

Good: Component or system is sound and performs its function, although it may show signs of normal wear and tear. Some minor rehabilitation work may be required.

Fair: Component or system falls into one or more of the following categories: a) Evidence of previous repairs not in compliance with commonly accepted practice, b) Workmanship not in compliance with commonly accepted standards, c) Component or system is obsolete, d) Component or system approaching end of expected performance. Repair or replacement is required to prevent further deterioration or to prolong expected life.

Poor: Component or system has either failed or cannot be relied upon to continue performing its original function as a result of having exceeded its expected performance, excessive deferred maintenance, or state of disrepair. Present condition could contribute to or cause the deterioration of other adjoining elements or systems. Repair or replacement is required.

Critical: Immediate repair/replacement recommended in less than 1 year. Physical deficiencies that require immediate action as a result of existing or potentially unsafe conditions, building code violations, poor or deteriorated conditions of a critical element or system, or a condition that if left "as is" would result in a critical element or system failure.

Priority

Urgent – Immediate repair/replacement recommended in less than 1 year. Physical deficiencies that require immediate action as a result of existing or potentially unsafe conditions, building code violations, poor or deteriorated conditions of a critical element or system, or a condition that if left "as is" would result in a critical element or system failure.

High – Repair/replacement anticipated within the first 2 years. Physical deficiencies including deferred maintenance that may not warrant immediate attention but require repairs or replacements that should be undertaken on a priority basis, taking precedence over routine preventive maintenance work within a zero to one-year time frame. Included are such physical deficiencies resulting from improper design, faulty installation, and/or substandard quality of original systems or materials. Components or systems that have exceeded their expected useful life that may require replacement to be implemented within a zero to one-year time frame are also included.

Medium - Repair/replacement is anticipated between 3 to 5 years.

Low - Replacement is not anticipated within the first 5 years.

Facility Condition ("FCI") Levels

Good Condition (0-5% FCI) – Asset is in reasonable condition and does not require capital expenditure.

Fair Condition (6-10% FCI) – Asset is deteriorating, requires capital expenditure and will likely become "poor" within a few years if not addressed.

Poor Condition (11-30% FCI) – Asset is deteriorated and requires immediate capital expenditure.

Critical (31% + FCI) – Asset is in disrepair or dilapidated and requires urgent significant capital expenditure.

Repair/Replacement Reserves - Non-routine maintenance items that will require significant expenditure over the timeframe of this study. Included are items that will reach the end of their estimated useful life during the term of the study or in the opinion of the consultant will require attention during that time. Items with estimated expenditures below \$5,000.00 are below the capital threshold for this study and may or may not be reported since it is anticipated that those items will be repaired/replaced within the scope of regular building maintenance. The recommended repairs will be scheduled appropriately over a 20-year period in 5-year intervals. All the prices quoted are in Canadian 2023 dollars and are presented in the Capital Expenditure Tables.

3.0 SYSTEMS AND OBSERVATIONS

Refer to **Appendix B**, Facility Condition Index Table for the estimated time-period of replacement or repairs and associated estimated costs.

3.1 Site Improvements

3.1.1 Paving & Curbing

Description

There is no paving or curbing. Not applicable.

3.1.2 Flatwork

Description

There is no flatwork on the site. Not applicable.

3.1.3 Landscaping & Appurtenances

Description

Landscaping on the site consists of grass and trees surrounding the structure.

Observations & Comments

Landscaping is in poor condition with plant overgrowth and unmaintained vegetation. A budget for plant and trees overgrowth trimming and removals has been allowed for during the time-period of this study.

3.2 Structure & Building Envelope

Due to safety concerns, we were not able to review conditions up close and interior.

3.2.1 Substructure

Description

We assume there are typical foundations.

Observations & Comments

We assume the substructure is in critical condition. A budget for replacement has been allowed for during the timeframe of this study as an urgent item.

3.2.2 Superstructure

Description

The building and roof are composed of standard wood framing with prefabricated trusses and bracing/support members.

Observations & Comments

The structural framing has collapsed and has failed. A budget for replacement has been allowed for during the timeframe of this study as an urgent item.

3.2.3 Exterior

Description

The exterior of the building is metal siding. There are wood windows, swing doors, and barn sliding doors.

Observations & Comments

The metal siding is damaged and collapsed and sections of the siding are missing. A budget for metal siding replacement has been allowed for during the timeframe of this report as an urgent item.

Windows and doors are missing and are boarded with wood. The large sliding doors are damaged. A budget for windows, doors and sealants replacement has been allowed for during the timeframe of this report as urgent items.

3.2.4 Roofing

Description

There is a sloped metal roof. The metal roof does not have sheathing/decking and is laid on the roof structure.

Observations & Comments

The metal roof is rusted, collapsed and in critical condition. A budget for replacement has been allowed for during the time-period of this study as an urgent item.

3.3 Mechanical Systems

3.3.1 Plumbing

Description

There is no plumbing system. Not applicable.

3.3.2 HVAC

Description

Ventilation fans are provided. These systems are abandoned and are non-operational.

Observations & Comments

The ventilation fans and systems are not operational. A budget for replacement has been allowed for during the timeframe of this study as an urgent item.

3.3.3 Electrical

Description

The electrical system is abandoned. Not applicable.

Observations & Comments

The electrical systems are disconnected and not operational. A budget for electrical systems replacement including installation of lighting and thermographic scanning has been allowed for during the timeframe of this study as an urgent item.

3.4 Special Systems

3.4.1 Security

Description

There is no security system. Not applicable.

3.4.2 Fire Protection & Life Safety

Description

There is no fire protection or life safety equipment. Not applicable.

3.5 Interior Elements

3.5.1 Finishes

Description

There are no interior finishes. Not applicable.

3.6 Miscellaneous

3.6.1 Maintenance & Other

Observations & Comments

Due to safety concerns, we were not able to review conditions up close and interior.

There could be asbestos and hazardous materials in the building. A budget for a Designated Substances Survey for items related to asbestos, mould and hazardous materials has been allowed as an urgent priority.

Planned maintenance is necessary for the longevity of assets and to control and reduce repair and replacement costs. Preventative maintenance work should be completed promptly.

From our observations we did not see anything that could not be repaired. There are some current items that require maintenance, but every building requires maintenance.

4.0 REPAIR/ REPLACEMENT RESERVES

Refer to **Appendix B, Schedule of Anticipated Reserve Requirements.**

5.0 LIMITATIONS

The information, observations, and conclusions described in this report are valid on the date of the report and have been made under the terms, conditions, limitations, and constraints noted in the report. We prepared the report for the exclusive use of the Client. No other individual or party shall be entitled to rely upon the report without our express written consent. If another individual or party relies on the report, such individual or party shall indemnify and hold Keller Engineering, formerly Criterium-Jansen Engineers, harmless for any damages, losses, or expenses incurred because of such use. Any use or reliance of the report by an individual or party other than the Client shall constitute acceptance of these terms and conditions. Any electronic copies of this report that are provided, are for the convenience of the Client, and are not to be construed as the original or final report.

The report is limited to the visual observations made during our review. We did not remove materials, conduct any destructive or invasive testing, move furnishings or equipment, or undertake any digging or excavation. Accordingly, we cannot comment on the condition of systems that we could not see, such as buried structures and utilities, nor are we responsible for conditions that could not be seen or were not within the scope of our services at the time of review. We did not undertake to completely assess the stability of the buildings or the underlying foundation soil since this effort would require excavation and destructive testing. Likewise, this is not a seismic assessment.

We do not render an opinion on uninspected portions of the facility.

We did not perform any computations or other engineering analysis as part of this evaluation, nor did we conduct a comprehensive code compliance investigation. We did not provide an environmental assessment or opinion on the presence of any environmental issues such as asbestos, hazardous wastes, toxic materials, the location, and presence of designated wetlands, IAQ, etc.

The report is not to be considered a warranty of condition, and no warranty is implied. The photographs are an integral part of this report and must be included in any review.

If opinions of probable costs are presented, they are preliminary only. Opinions are based on our general knowledge of building systems and the contracting/construction industry. When appropriate, we have relied on standard sources, such as Means Building Construction Cost Data, to develop opinions of probable costs. However, for some items for which we have developed opinions of probable costs (e.g., structural repairs), no standard guide for developing such costs exists. It is not the intent of the BCA to provide/prepare exact quantities or identify the exact locations of items or systems as a basis for preparing the opinions of costs.


We have performed no design work as part of the study, nor have we obtained competitive quotations or estimates from contractors as this also is beyond the scope of the project. The actual cost to remedy deficiencies and deferred maintenance items that we have identified may vary significantly from estimates and competitive quotations from contractors.

This report has been prepared in strict confidence. No reproduction or reuse is permitted without express written consent. Furthermore, we will not release this report to anyone without your permission. If you have any questions about this report or review, please call.

Thank you for the opportunity to be of assistance to you.


Report Prepared by:

Jaime Rodríguez, B.Tech. (Arch.Sc.),
C.E.T., RRO
Senior Project Manager



Report Reviewed by:

Jim Rammos, P.Eng.
Director, Building Science &
Restoration



APPENDIX A

SELECTED PHOTOGRAPHS

Location:
351028 17th Line
East Garafraxa, ON

Photo Taken by:
Jaime Rodriguez
Emma Bresil

Date:
October 24, 2023



Description:

South and west sides of the third shed.

The shed has metal siding, sloped metal roof with vents, sheet metal flashings, wood windows, service doors and sliding barn doors.

There are ventilation fan hoods along the exterior wall.

The windows are boarded up.

The building is dilapidated and is abandoned.

Photo Number

1



Description:

North elevation.

The metal roof and building structure is collapsed. The building is in failure mode.

The shed is surrounded by plant overgrowth.

Photo Number

2

Location:
351028 17th Line
East Garafraxa, ON

Photo Taken by:
Jaime Rodriguez
Emma Bresil

Date:
October 24, 2023



Description:

All building components and systems not safe and is no longer functional.

The metal roof is detached, the structure is missing siding and the large sliding door.

Due to safety concerns, we were not able to review conditions up close and the interior.

Photo Number

3



Description:

All building components and systems not safe and is no longer functional.

The metal roof is detached, the structure is missing siding and the large sliding door.

Due to safety concerns, we were not able to review conditions up close and interior.

The structure is in critical condition.

Photo Number

4

APPENDIX B

FACILITY CONDITION INDEX

Facility Condition Index Table

NA = Not Anticipated during the timeframe of the report based on the condition at the time of the study.

BLW = Below Capital Threshold

The recommendations and comments included in this report are based on the collective experience of Keller Engineering. Any costs or other comments contained herein do not necessarily infer that subcontracts, quotes, or opinions of other professionals were solicited.

This table summarizes probable costs of repairs or replacements, including both labor and materials. These costs are based on our general knowledge of building systems, local contracting/construction industry conditions, and other sources such as Means Building Construction Cost Data. We have performed no design work as part of this study, nor have we obtained competitive quotations or estimates. Costs are uninfated.

Condition Values:

1. 0-10 Excellent. "As new" condition.
2. 11-30 Good. Sound an performs its function.
3. 31-60 Fair. Repair or replacement may be required to prolong life.
4. 61-80 Poor. Component has failed or cannot be relied on to perform function.
5. >81 Critical. Immediate repair/replacement is less than 1 year and may relate to safety or code violations.

**Township of East Garafraxa - Shed 2 at Gravel Pits
351028 17th Line, East Garafraxa**

REPAIR/REPLACEMENT RESERVES

ITEM	DESCRIPTION	UNIT COSTS & TIME-PERIOD ESTIMATES						CONDITION ESTIMATE		ANTICIPATED PRIORITY			PREDICTED LIFE CYCLE				
		URGENT	YEARS 1 - 5	YEARS 6 - 10	YEARS 11 - 15	YEARS 16 - 20	TOTAL	CONDITION LEVEL	CONDITION VALUE	IMPORTANCE WEIGHTING SCALE	PRIORITY VALUE INDEX	PRIORITY LEVEL	INCEPTION YEAR (ESTIMATED)	ACTUAL AGE	LIFE EXPECTANCY	OBSERVED AGE	REMAINING LIFE EXPECTANCY
		2023	2024 - 2028	2029 - 2033	2034 - 2038	2039 - 2043	20 YEAR										
1.0 SITE IMPROVEMENTS																	
1.1 Paving	Not applicable						\$ -	-	-	-	-	-	-	-	-	-	-
1.2 Flatwork	Not applicable						\$ -	-	-	-	-	-	-	-	-	-	-
1.3 Landscaping	Plants - Sod - Overgrowth - Trimming/removals - BLW						\$ -	Poor	80	10	38	Medium	1978	45	100	45	55
2.0 STRUCTURE & BUILDING ENVELOPE																	
2.1 Substructure	Foundations - Replacement	\$ 100,000					\$ 100,000	Critical	81	60	73	High	1978	45	100	100	0
2.2 Superstructure	Structural Framing - Wood - Columns, Beams and Prefabricated Trusses - Replacement	\$ 100,000					\$ 100,000	Critical	81	60	73	High	1978	45	100	100	0
	Structural Study - Review & Reporting	\$ 150,000					\$ 150,000	-	-	-	-	-	-	-	-	-	-
2.3 Exterior	Walls, Siding, Sheet Metal & Sealants - Replacement	\$ 100,000					\$ 100,000	Critical	85	40	67	High	1978	45	40	45	0
	Barn Doors, Doors & Weatherstripping - Sliding - Replacement	\$ 20,000					\$ 20,000	Critical	85	30	63	High	1978	45	40	45	0
	Windows & Frames - Replacement	\$ 5,000					\$ 5,000	Critical	85	50	71	High	1978	45	30	45	0
2.4 Roofing	Sloped Metal Roof & Sheet Metal- Replacement	\$ 100,000					\$ 100,000	Critical	85	30	63	High	1978	45	40	45	0
3.0 MECHANICAL SYSTEMS																	
3.1 Plumbing	Not applicable						\$ -	-	-	-	-	-	-	-	-	-	-
3.2 HVAC	Ventillation Fans (Chore-Time) Systems - Replacement		\$ 10,000				\$ 10,000	Critical	85	20	59	High	1978	45	20	40	0
3.3 Electrical	Distribution & Wiring Systems - Replacement & Thermographic Scanning	\$ 25,000					\$ 25,000	Critical	85	60	75	High	1978	45	10	40	0
4.0 SPECIAL SYSTEMS																	
4.1 Security	Not applicable						\$ -	-	-	-	-	-	-	-	-	-	-
4.2 Fire & Life	Not applicable						\$ -	-	-	-	-	-	-	-	-	-	-
5.0 INTERIOR ELEMENTS																	
5.1 Finishes	Metal Wall & Ceiling Panels - Replacement		\$ 100,000				\$ 100,000	Critical	85	20	59	High	1978	45	40	45	0
6.0 MISCELLANEOUS																	
6.1 Other	DSS	\$ 10,000					\$ 10,000	-	-	-	-	-	-	-	-	-	-

FACILITY CONDITION INDEX (FCI)						
Estimated Current Replacement Value of Building	\$ 450,000					
	IMMEDIATE	YEARS 1 - 5	YEARS 6 - 10	YEARS 11 - 15	YEARS 16 - 20	TOTAL
	2023	2024 - 2028	2029 - 2033	2034 - 2038	2039 - 2043	
Current Aggregated Total Costs Estimate	\$ 610,000	\$ 110,000	\$ -	\$ -	\$ -	\$ 720,000
Inflated Aggregated Total Costs	\$ 624,030	\$ 112,530	\$ -	\$ -	\$ -	\$ 736,560
CURRENT FCI	136%	24%	0%	0%	0%	160% CRITICAL
FCI Classifications:						
1. FCI = 0-5% Good Condition. Asset in reasonable condition and does not require capital expenditure						
2. FCI = 6-10% Fair Condition. Asset is deteriorating, requires capital expenditure and will likely become "poor" within a few years if not addressed.						
3. FCI = 11-30% Poor Condition. Asset is deteriorated and requires immediate capital expenditure.						
4. FCI = > 31% Critical Condition. Asset is in disrepair or dilapidated and requires urgent significant capital expenditure.						

APPENDIX C

RESUMES

25 First Street
Orangeville, Ontario L9W 2C8
Tel: 519-940-0571
Email: info@kellerengineering.com



Jim Rammos, P.Eng., IEEE ~ CURRICULUM VITAE

AREAS OF EXPERTISE

Mr. Rammos has extensive knowledge and experience in the Building Science and Forensics industry. His specific areas of expertise include building science, thermographic scanning, mechanical & electrical engineering, new and restoration construction, reserve fund studies, performance audits, mechanical & electrical systems designs and assessments.

QUALIFICATIONS

Keller Engineering, located in Orangeville, Ontario services Southern Ontario and South Saskatchewan. We specialize in building inspection and commercial real estate consulting services. Our firm is a consulting engineering company that combines the resources of engineering leaders with the service and responsiveness of your own dedicated, local firm. With broad expertise and carefully controlled standards of quality our engineers provide a resource base that offers our clients the highest quality engineering evaluations.

Keller Engineering services encompass investigations and analyses vital to property acquisition and management, including: Due Diligence Reports, Property Condition Assessments, Reserve Studies, Performance Audits, Environmental Site Assessments, Construction Plan and Cost Reviews, Construction Loan Monitoring, Construction Quality Inspections, Structural Investigations, Facilities Management Consulting, Forensic Engineering, Insurance Investigations, and Design and Related Services.

Jim Rammos, P.Eng., IEEE is a Senior Engineer at Keller Engineering. Mr. Rammos is a licensed Professional Engineer in the province of Ontario and has over 25 years of engineering experience. To complement his portfolio of work Mr. Rammos also works with our clients to complete restoration work, building condition assessments, capital replacement studies and is a certified thermographer to complete electrical thermographic scanning and energy audits.

25 First Street
Orangeville, Ontario L9W 2C8
Tel: 519-940-0571
Email: info@kellerengineering.com



EDUCATION

- Bachelor of Technology (B.Tech.), Ryerson Polytechnical University, Toronto, ON
- Bachelor of Engineering (B.Eng.), University of Toronto, Toronto, ON
 - Major: Mechanical Engineering
- Bachelor of Applied Science (B.A.Sc.), University of Toronto, Toronto, ON
 - Major: Electrical Engineering
- Professional Engineer, Professional Engineers Ontario, licensed since 1995
- BCIN – Building Code Identification Number 35394
- Certified Thermographer – Level 1, since 2007

PROFESSIONAL REGISTRATIONS

Licensed, Association of Professional Engineers of Ontario (PEO)
American Society of Heating, Refrigeration & Air-Conditioning Engineers (ASHRAE)
Canadian Society for Mechanical Engineers (CSME)
Canadian Automated manufacturing Society (CAMS)
Institute of Electronics & Electrical Engineers (IEEE)
Ontario Building Envelope Council (OBEC)

Jaime Rodríguez, B.Tech. (Arch.Sc.), C.E.T., RRO ***~ CURRICULUM VITAE***

AREAS OF EXPERTISE

Mr. Jaime Rodriguez specializes in building science and building envelope engineering. Jaime provides design & replacement/repair planning, quality control, building envelope forensics, diagnostic testing, and contract management services. He is primarily engaged in engineering project management, providing technical expertise, and building science/engineering design and property condition assessments.

QUALIFICATIONS

Keller Engineering, located in Orangeville, Ontario services Southern Ontario and South Saskatchewan. We specialize in building inspection and commercial real estate consulting services. Our firm is a consulting engineering company that combines the resources of engineering leaders with the service and responsiveness of your own dedicated, local firm. With broad expertise and carefully controlled standards of quality our engineers provide a resource base that offers our clients the highest quality engineering evaluations.

Keller Engineering services encompass investigations and analyses vital to property acquisition and management, including: Due Diligence Reports, Property Condition Assessments, Reserve Studies, Performance Audits, Environmental Site Assessments, Construction Plan and Cost Reviews, Construction Loan Monitoring, Construction Quality Inspections, Structural Investigations, Facilities Management Consulting, Forensic Engineering, Insurance Investigations, and Design and Related Services.

Jaime Rodríguez is Senior Project Manager at Keller Engineering. Mr. Rodriguez is a Certified Engineering Technologist in the Province of Ontario and has over 20 years of engineering experience. Jaime has effective problem-solving skills that provide practical engineering, project management & field applied solutions.

EDUCATION

- Bachelor of Technology (B.Tech.), Ryerson University, Toronto, ON

PROFESSIONAL REGISTRATIONS

Certified Engineering Technologist, Ontario Association of Engineering Technicians and Technologists (OACETT).

International Institute of Building Enclosure Consultants (IIBEC), RRO Designation.